

AD720319

Technical Note N-1148

AIRFIELD PAVEMENT CONDITION SURVEY,  
USNAS POINT MUGU, CALIFORNIA

By

D. J. Lambiotte and R. B. Brownie

February 1971

Reproduced by  
NATIONAL TECHNICAL  
INFORMATION SERVICE  
Springfield, Va 22151

Approved for public release, distribution unlimited.

NAVAL CIVIL ENGINEERING LABORATORY  
Port Hueneme, California 93043

Technical Note N-1148

53-125

by

D. J. Lambiotte and R. B. Brownie

## ABSTRACT

The results of a condition survey of the airfield pavements at the U. S. Naval Air Station, Point Mugu, California are presented. The survey established statistically-based condition numbers (weighted defect densities) which were direct indicators of the condition of the individual asphaltic concrete and portland cement concrete pavement facilities. Additional evaluation efforts included photographic coverage of defect types, preparation of the construction history of the station, compilation of data on current aircraft traffic and aircraft types using the station, performance of runway skid resistance tests, and a study of the requirements for future pavement evaluation efforts.



Approved for public release, distribution unlimited.

## CONTENTS

	page
INTRODUCTION . . . . .	1
BACKGROUND . . . . .	1
CONSTRUCTION HISTORY . . . . .	1
CURRENT AIRCRAFT TRAFFIC . . . . .	2
CONDITION SURVEY PROCEDURES . . . . .	2
Step 1. Preliminary Survey . . . . .	2
Step 2. Statistical Sampling and Defect Survey . . . . .	3
Step 3. Defect Severity Weighting System . . . . .	4
Step 4. Facility Summary--Weighted Defect Densities . . . . .	4
GENERAL COMMENTS ON CONDITION SURVEY PROGRAM . . . . .	5
RESULTS OF CONDITION SURVEY . . . . .	6
RESULTS OF ASSOCIATED FIELD TESTS . . . . .	7
RECOMMENDATIONS FOR FURTHER EVALUATION EFFORTS . . . . .	7
Table 1. Aircraft Operations Data . . . . .	8
Table 2. Aircraft Using USNAS Point Mugu, California . . . . .	9
Table 3. Defect Severity Weights . . . . .	10
Figure 1. Aerial Photo of USNAS Point Mugu, California . . . . .	11
Figure 2. Discrete Area Map . . . . .	12
Figures 3 & 4. Sampling Guides . . . . .	13
Figures 5 - 23. Photographs of Pavements at USNAS Point Mugu, California . . . . .	15
DISCRETE AREA DEFECT SUMMARY SHEETS . . . . .	35
Portland Cement Concrete . . . . .	37
Asphaltic Concrete . . . . .	55
FACILITY DEFECT SUMMARY SHEETS . . . . .	75
Portland Cement Concrete . . . . .	77
Asphaltic Concrete . . . . .	79
Appendix A. Construction History . . . . .	83
Figure A-1. Construction History Drawing . . . . .	94
REFERENCES . . . . .	95

## INTRODUCTION

In October, 1969, the Naval Facilities Engineering Command authorized a series of periodic pavement condition surveys to be conducted at Naval and Marine Corps air stations. The purpose of this condition survey task is to determine the suitability of the airfield pavement surfaces for aircraft operational requirements and to establish a uniform basis for maintenance and repair efforts. During the month of August, 1970, a pavement condition survey was conducted at the Naval Air Station, Point Mugu, California. The survey consisted of a sophisticated, statistically-based procedure of pavement defect identification and defect measurement which permitted the establishment of condition numbers (weighted defect densities) which are direct indicators of the surface condition of the asphaltic concrete (AC) and/or portland cement concrete (PCC) airfield pavement facilities. Though different survey techniques were used for the two pavement types, the resulting defect densities often were similar numerically. However, this was coincidental. The defect densities for the two types of pavement are incompatible and must be considered separately. Additional survey efforts included photographic coverage of defect types, preparation of the construction history of the station, compilation of data on current aircraft traffic and aircraft types using the station, performance of runway skid resistance tests, and delineation of requirements for future pavement evaluation efforts at the station.

## BACKGROUND

The U. S. Naval Air Station, Point Mugu, is located in Ventura County, ten miles south of Oxnard, California, at an elevation of 13 feet. An aerial photograph of the station is shown in Figure 1. The airfield has two runways, 3-21 and 9-27, which are, respectively, 11,100 and 5,500 feet long.

## CONSTRUCTION HISTORY

Original construction of Runway 9-27 consisting of a 5,500 foot strip of pierced steel planking (Marston Matting) was completed in 1944. In 1950, a new asphaltic concrete runway, associated taxiways, and parking apron were constructed on top of the pierced steel plank. In 1952, a major runway (3-21), 7,100 feet in length, and associated



taxiways were constructed. Additional parking aprons were constructed during the following years, and Runway 3-21 and its associated taxiways were extended to 11,100 feet in 1960. A complete history of pavement construction is presented in Appendix A.

#### CURRENT AIRCRAFT TRAFFIC

A tabulation of the number of aircraft operations for a 12-month period is shown in Table 1. Table 2 lists the aircraft normally based at the station and transient aircraft observed using the station during the period of evaluation and the parking aprons used for each type of aircraft.

#### CONDITION SURVEY PROCEDURES

The condition survey procedures used in this study are as follows:

##### Step 1. Preliminary Survey

In the preliminary survey the evaluators made a general and personal inspection of all airfield pavement areas, during which they noted the type and distribution of defects in each facility (runway, taxiway, etc). In addition, a previously-prepared construction history was consulted and areas of different construction and different pavement type (AC or PCC) within a facility were noted. As a result of these efforts, each pavement facility was then divided into "discrete areas" of reasonably similar failure modes for performance of the subsequent sampling and tally or measurement of defects. Thus, if the type and/or number of defects found in one portion of a facility were distinctly different from those found in another portion of that facility, discrete areas were selected on this basis. If, however, the pavement facility contained few defects or if the defects found were similar in type and distribution throughout the facility, each facility was individually divided for survey according to the construction history. Under either criterion, a discrete area may vary, for example, from a 500 foot length of runway or taxiway to the entire length of the facility. Discrete areas selected at NAS Pt. Mugu are shown in Figure 2. Note that all discrete areas are numbered with a system that relates the discrete area to the runway, taxiway, etc., of which it is a part. For example, discrete areas comprising Runway 3-21 are designated R3-1 and R3-2, respectively; discrete areas for Taxiway 3 are T3-1 and T3-2, and so on.

A special survey of singular occurrences of serious defects was made during the preliminary survey. This is necessary because the statistical sampling techniques utilized in the subsequent survey are effective in spotting defects only when such defects are numerous and/or relatively well distributed. This abbreviated special survey

provided information on those infrequent defects, if any, which may present a problem to safe aircraft operation.

## Step 2. Statistical Sampling and Defect Survey

After selection of discrete areas, a number of small "sample areas" were chosen within each discrete area. The total number of sample areas was determined by statistical theory, as a function of the relative size of the discrete area. Actual locations of the sample areas were selected at random from the discrete area.

Sample areas in PCC pavements basically consisted of individual slabs, usually  $12\frac{1}{2} \times 15$  feet in size. For the convenience of the evaluators, either a single slab or a number of adjacent slabs can be considered as a sample area. Both types of sampling area are shown in schematic in Figure 3. Note from Figure 3 that individual sample slabs and/or sample strips were selected within the center 100 feet (laterally) of runways and within the center 50 feet (laterally) of taxiways by a random selection process. For parking aprons, mats, etc., similar sample areas were selected at random over the entire pavement area.

For AC pavements, sample areas were fifty foot square areas, located as shown in Figure 4. For parking aprons, mats, etc. (not shown in Figure 4) sample areas were fifty feet square, as for other traffic areas, and randomly located over the entire pavement area.

All defects or defected slabs in each of the selected sample areas were noted on appropriate data sheets. For PCC pavement slabs or sample strips either single or multiple occurrences of a given defect type within the slab qualified the slab as a defected slab. For example, one or more spalls qualified a slab as a spalled slab. A crack in the same slab required that it be counted again, this time as a cracked slab. No measurement of length, area, etc., was recorded for PCC pavement defects. When a sample slab strip was chosen for test, the above mentioned tally method (slab by slab) was still utilized.

The defects found in AC sample areas were measured and tallied, rather than merely tallied as were those for PCC pavements. Depending on the type of defect, the total length in feet (for cracks, etc.) or total area in square feet (for pattern cracking, raveling, etc.) was recorded.

The above survey of defects found in sample areas (in each discrete area) are shown in column (c) of the Discrete Area Defect Summary sheets, pages 35 through 74 of this report. Separate summary sheets are provided for portland cement concrete (PCC) and asphaltic concrete (AC) pavements. Total defect counts for the entire discrete area were calculated by a linear extrapolation of the defect data in column (c), and are shown in column (d) of the Discrete Area Defect Summary sheets. To remove the influence of the size of the discrete area on the total defect count (i.e., the bigger the area, the larger the defect count), the total defect count was divided by either the number of slabs in the

discrete area (for PCC pavements) or by the area (in 10 square foot increments) of the discrete area (for AC pavements). This gives a defect density (per slab or per 10 square feet) which is listed in column (e).

### Step 3. Defect Severity Weighting System

A weighting system, providing a numerical weight for each type defect in proportion to the relative severity of that defect, was applied in the following manner to each of the defect counts in the discrete area:

$$\text{given defect density} \times \frac{\text{weight for that type defect}}{\text{type defect}} = \text{weighted defect density}$$

This is accomplished in columns (f) and (g) of the Discrete Area Defect Summary sheets. Next, a total weighted defect density is obtained for each discrete area by summing column (g) of these sheets. Note that a letter suffix is added to each total weighted defect density for the purpose of further distinguishing between asphaltic concrete defect densities (suffix "A") and portland cement concrete defect densities (suffix "C").

The defect weighting guide developed by NCEL assigns greater weights to defects that (1) presently affect the safe operation of aircraft or the cost of aircraft operation; (2) will lead to increased airfield pavement maintenance costs; or (3) will result in significant deterioration of load-carrying capacity of the pavements. The resultant numerical weights were further modified to reflect variations in pavement environment from station to station. For example, higher (more severe) weights were assigned to defects which are affected by factors such as freezing weather, heavy rainfall, or blow sand for surveys of airfields located in areas where these undesirable environmental effects occur. Thus, it can be seen that the higher the numerical weighted defect density, the poorer the condition of the surveyed pavement. Defect severity weights used in calculating weighted defect densities at NAS Pt. Mugu are given in Table 3.

Remarks concerning the general pavement condition and the defects identified are given in narrative form on each Discrete Area Summary sheet. In addition, photographs of typical pavement conditions noted during the survey can be seen in Figures 5 through 23.

### Step 4. Facility Summary--Weighted Defect Densities

A final step in providing a numerical condition rating for each facility (runway, taxiway, etc.) is accomplished in the Facility Defect Summary sheets, pages 75 through 81 of this report. Again note that separate sheets have been provided for AC and PCC pavements.

In these sheets the individual weighted defect densities for all discrete areas comprising the entire AC or PCC portion of a facility (runway, taxiway, etc.) are summarized in column (a). When an AC or PCC facility (or portion) has been divided into more than one discrete area for the condition survey, the proportional contribution of each discrete area to the entire AC or PCC facility area is determined in column (b). In column (c) these proportions are applied to the individual discrete area weighted defect densities listed in column (a) and added to obtain an overall average weighted defect density for the entire AC or PCC portion of the facility (marked "Total" in column (c)). When an entire AC or PCC facility (or portion) has been designated as a single discrete area (as often occurs), the proportionality factor in column (b) is obviously 1.00 and the discrete area weighted defect density from column (a) becomes the average weighted defect density for the entire facility (or portion) in column (c).


#### GENERAL COMMENTS ON CONDITION SURVEY PROGRAM

The weighted defect densities, listed in column (a) of the Facility Defect Summary for individual discrete pavement areas and in column (c) as averaged weighted defect densities for entire AC or PCC runways, taxiways, etc. (or portions thereof) represent, numerically, the surface condition of the airfield pavements at the station. As previously stated, the larger defect density numbers indicate basically a greater number and/or severity of defects per unit area of pavement, i.e., a poorer pavement. Thus, they represent the final product of the pavement condition survey. It should be noted specifically, however, that AC and PCC pavement defect densities, although often numerically similar, are obtained by two different condition survey techniques and, as such, are not numerically compatible and must not be combined. (It is largely because of this fact that the letter suffixes "A" and "C" have been affixed to defect densities for AC and PCC pavements respectively.) As an example consider the common case of an AC runway with PCC ends. The condition survey system presented herein provides individual discrete area weighted defect densities for discrete areas selected on both AC and PCC pavements, but provides a separate average weighted defect density for the combined PCC end pavements. It is not possible to combine these defect densities to obtain an averaged AC/PCC defect density for the entire runway. Thus the defect densities for AC and PCC are reported separately, given different letter suffixes, and should include the letter suffix when reference is made to them.

Individual numerical defect densities, however accurately they indicate pavement condition, may mean little to the reader of an individual airfield condition survey report, for he has no basis upon which to judge the relative severity of pavement condition associated with the numbers obtained for his pavements. The primary value of a

numerical condition survey program will be the accumulation of uniformly-obtained, comparative condition data for many airfields which can best be correlated, studied, and used in the decision-making processes at headquarters levels.

For the benefit of the individual reader, however, an effort was made during the first year of pavement condition surveys (FY-70) to relate the numerical condition (defect densities) to the basic subjective condition descriptors (excellent, good, fair, poor, etc.) used in all previous Navy pavement evaluation procedures. Although the subjective, condition-descriptor approach is poorly regarded as a means of comparing pavement condition from one airfield to another, the following diagram may serve temporarily as a rudimentary bridge between the old subjective system and the new (numerical) condition approach:



The numerical defect densities presented in this report were developed to aid in determining the suitability of the airfield pavement surfaces for aircraft operational requirements and to establish an unbiased, uniform basis for initiating maintenance and repair efforts. As such, defect densities are simply visually-determined indicators of the condition of the pavement and do not represent true "condition ratings" in that they do not include factors relating to pavement strengths, traffic usage, etc. It is possible that additional measurements or modifications may be considered necessary or desirable in future condition survey programs.

#### RESULTS OF CONDITION SURVEY

Weighted defect densities for discrete areas selected on AC pavements at NAS Pt. Mugu ranged from 0.00A (no defects visible) for the best AC discrete area to a worst defect density of 26.50A for a portion of Parking Apron 6. Average weighted defect densities for entire AC portions of the runways at NAS Pt. Mugu were 0.00A for Runway 3-21 and 0.96A for Runway 9-27.

Weighted defect densities for discrete areas selected on PCC pavements ranged from 0.22C for the best PCC discrete area (for a portion of Runway 9-27) to a worst defect density of 8.17C (for a portion of Parking Apron 2A). Average weighted defect densities for entire PCC portions of runways at the station were 0.22C for Runway 9-27 and 2.93C for Runway 3-21.

#### RESULTS OF ASSOCIATED FIELD TESTS

In order to determine the skid resistance characteristics of the runway pavements at NAS Pt. Mugu, vehicle braking tests were performed using a calibrated decelerometer. Tests were conducted at selected locations on Runway 3-21, at a vehicle speed of 30 miles per hour, and on a wet pavement. Decelerometer readings averaged 27.3 feet per second on the asphaltic concrete and 22.6 feet per second on the portland cement concrete. These readings equate to a friction coefficient between tire and pavement of 0.85 and 0.70, respectively.

Although the Navy, at present, has no official standard or specification for pavement skid resistance, a study of the literature, coupled with the results of limited skid resistance testing performed by NCEL in recent years, indicates that friction coefficients higher than 0.5 may be considered generally acceptable for airfield pavements. Thus, the pavements at NAS Pt. Mugu exhibited an acceptable degree of skid resistance.

#### RECOMMENDATIONS FOR FURTHER EVALUATION EFFORTS

A pavement evaluation was performed at NAS Pt. Mugu by NCEL in 1965 (see reference 1). No further evaluation effort is recommended at this time.

Table 1. Aircraft Operations Data USNAS  
Point Mugu, California.

August 1969	5,740
September	5,242
October	7,059
November	6,511
December	5,186
January 1970	5,259
February	7,551
March	10,163
April	7,622
May	9,101
June	8,500
July	7,305
Average operations per month	7,103
Estimated percent of operations by aircraft over 20,000 pounds single gear load:	75%

**Table 2. Aircraft Using USNAS Point Mugu, California.**

<b>Parking Apron 1</b>	<b>Used for auto parking</b>
<b>Parking Apron 1A</b>	<b>A4, A7, F4, F8, F9, T33, E2A</b>
<b>Parking Apron 2</b>	<b>P2, S2, C130, T28</b>
<b>Parking Apron 2A</b>	<b>A3, A4, F4, F8, F86, C47, C54, C121, C130, C141, P2, P3, S2, BOEING 707</b>
<b>Parking Apron 3</b>	<b>UH 34</b>
<b>Parking Apron 3A</b>	<b>B47, C130</b>
<b>Parking Apron 4</b>	<b>A3, P2, S2, C131</b>
<b>Parking Apron 5</b>	<b>Aircraft taxi through PA5 to PA3A</b>
<b>Parking Apron 6</b>	<b>C130, HH3</b>





Table 3. Defect Severity Weights  
Airfield: USNAS Point Mugu, California

Asphaltic Concrete		Portland Cement Concrete	
<u>Defect</u>	<u>Weight</u>	<u>Defect</u>	<u>Weight</u>
Depression . . . . .	9.0	Depression. . . . .	9.0
Rutting . . . . .	9.0	Shattered Slab. . . . .	9.0
Broken-up Area . . . . .	9.0	Faulting. . . . .	8.5
Faulting . . . . .	8.5	Spalling. . . . .	7.5
Raveling . . . . .	7.0	Scaling . . . . .	7.0
Erosion-Jet Blast. . . . .	7.5	"D-Line" Cracking . . . . .	6.5
Longitudinal, Transverse, or Longitudinal Construc- tion Joint Crack . . . . .	2.5	Pumping . . . . .	3.5
Pattern Cracking . . . . .	2.5	Poor Joint Seal . . . . .	2.5
Patching . . . . .	3.0	Corner Break. . . . .	2.5
Reflection Crack . . . . .	1.0	Intersecting Crack. . . . .	2.5
Oil Spillage . . . . .	1.5	Longitudinal or Transverse Crack . . . . .	1.0



**Figure 1. Aerial view, USNAS Point Mugu, California.**





Typical Runway

Typical Taxiway

Figure 3. Portland cement concrete sample areas.




Figure 4. Asphaltic concrete sample areas.



Figure 5. Repaired jet blast spalls, discrete area R3-2.



Figure 6. Failed corner spall repair, discrete area T3-2.





Figure 7. Missing joint seal, discrete area PA2-2.





Figure 8. Missing and poorly bonded joint seal, discrete area PA2A-1.



Figure 9. Severe joint spall, discrete area PA2A-3.



Figure 10. Severe corner spall and missing joint seal, discrete area PA2A-4.






Figure 11. Shattered slabs, discrete area PA4-4.




Figure 12. General view showing the excellent condition of discrete area R3-1.



Figure 13. Unsealed longitudinal construction joint crack, discrete area R9-1.





Figure 14. View of oil or fuel spillage, discrete area T3-1.




Figure 15. Faulting along taxiway edge, discrete area T9-1.






Figure 16. Pattern cracking, discrete area CTA-1.




Figure 17. Longitudinal and transverse cracks, discrete area PA2-1.




Figure 18. Pattern cracking, discrete area PA3-1.






Figure 19. Severe pattern cracking, discrete area PA4-1.



Figure 20. Unsealed longitudinal and transverse cracks, discrete area PA4-2.




Figure 21. Rutting and pattern cracking, discrete area PA5-1.





Figure 22. Surface softened by fuel or oil spillage, discrete area PA6-2.




Figure 23. Pattern cracking, discrete area PA6-2.



PORTLAND CEMENT AND ASPHALTIC CONCRETE  
DISCRETE AREA DEFECT SUMMARY SHEETS

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Runway 3-21  
Discrete Area R3-2 Total Slabs in Discrete Area (a) 528  
No. of Slabs Sampled (b) 132 Ratio a/b = 4.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect: c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	50	200	0.379	7.5	2.84
Scaling					
Shattered Slab					
Joint Seal	132	528	1.000	2.5	2.50
Pumping					
"D-line" cracking					

Remarks on Pavement Condition Total 5.34C

Spalls were up to 6 inches wide and some contained loose chunks. The joint seal was hardened and occasionally was missing in strips up to 2 feet long. Severe surface spalling due to jet blast had taken place at the west end of the runway. Approximately 95% of the surface spalls were repaired. See Figure 5.

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Runway 3-21  
Discrete Area R3-3 Total Slabs in Discrete Area (a) 1920  
No. of Slabs Sampled (b) 174 Ratio a/b 11.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	20	220	0.115	7.5	0.86
Scaling					
Shattered Slab					
Joint Seal	97	1067	0.556	2.5	1.39
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total 2.25C
The primary joint seal defect was loss of bond in transverse joints. Some burning and blowing of sealant occurred in the FCLP area. Spalls were generally less than 1 inch wide and 3 inches long.					

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Runway 9-27

Discrete Area R9-3 Total Slabs in Discrete Area (a) 136

No. of Slabs Sampled (b) 34 Ratio a/b = 4.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect : c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	1	4	0.029	7.5	0.22
Scaling					
Shattered Slab					
Joint Seal					
Pumping					
"D-line" cracking					
Remarks on Pavement Condition				Total	0.22C ***
Spalls were less than 1/2 inch wide.					

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Taxiway 3  
Discrete Area T3-2 Total Slabs in Discrete Area (a) 132  
No. of Slabs Sampled (b) 33 Ratio a/b = 4.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect: c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	5	20	0.152	7.5	1.14
Scaling					
Shattered Slab					
Joint Seal	33	132	1.000	2.5	2.50
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total 3.64C ***
Spalls occurred primarily on corners and transverse expansion joints. Spalls were up to 8 inches wide and exhibited loose material. Joint seal was shriveled and had lost bond. See Figure 6.					

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement



PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Taxiway 21  
Discrete Area T21-1 Total Slabs in Discrete Area (a) 1012  
No. of Slabs Sampled (b) 168 Ratio a/b = 6.02

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect: c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	10	60.20	0.0595	7.5	0.45
Scaling					
Shattered Slab					
Joint Seal					
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total 0.45C ***
Spalls were generally small, less than 1 inch wide on joints and 2 inches on corners.					

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Taxiway 9-27  
Discrete Area T9-2 Total Slabs in Discrete Area (a) 172  
No. of Slabs Sampled (b) 43 Ratio a/b = 4

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	3	12	0.070	7.5	0.53
Scaling					
Shattered Slab					
Joint Seal					
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total 0.53C
Spalls were less than 1 inch wide.					

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix (C) represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Connecting Taxiway 7

Discrete Area CT7-2 Total Slabs in Discrete Area (a) 40

No. of Slabs Sampled (b) 40 Ratio a/b = 1.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect: c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	22	22	0.550	7.5	4.13
Scaling					
Shattered Slab					
Joint Seal	40	40	1.000	2.5	2.50
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total 6.63C
Spalls were up to 2 inches wide and were located primarily on longitudinal construction joints. Joint seal was often missing and had generally lost bond.					

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Connecting Taxiway A  
Discrete Area CTA-2 Total Slabs in Discrete Area (a) 132  
No. of Slabs Sampled (b) 33 Ratio a/b = 4.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect: c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	3	12.0	0.091	7.5	0.68
Scaling					
Shattered Slab					
Joint Seal	31	124	0.939	2.5	2.35
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total 3.03C ***
Joint seal was shriveled and contained many embedded stones. Spalls were up to 1 inch wide.					

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 1A  
Discrete Area PA1A-1 Total Slabs in Discrete Area (a) 2216  
No. of Slabs Sampled (b) 185 Ratio a/b = 12.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect: c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break	4	48	0.022	2.5	0.06
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	52	624	0.282	7.5	2.12
Scaling					
Shattered Slab					
Joint Seal	185	2216	1.000	2.5	2.50
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total 4.68C

Joint seal was hardened and had lost bond. The spalls were generally small, less than 1 inch wide.

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement



PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 2

Discrete Area PA2-2 Total Slabs in Discrete Area (a) 240

No. of Slabs Sampled (b) 60 Ratio a/b = 4.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect: c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C. *	4	16	0.067	1.0	0.07
I.C. **					
Depression					
Spalling	16	64	0.267	7.5	2.00
Scaling					
Shattered Slab					
Joint Seal	60	240	1.000	2.5	2.50
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total 4.57C ***
Spalls were up to 3 inches wide. Joint seal had lost bond and was occasionally missing. See Figure 7.					

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 2A  
Discrete Area PA2A-1 Total Slabs in Discrete Area (a) 1845  
No. of Slabs Sampled (b) 185 Ratio a/b = 10.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect : c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*	3	30	0.016	1.0	0.02
I.C.**					
Depression					
Spalling	32	320	0.173	7.5	1.30
Scaling					
Shattered Slab					
Joint Seal	185	1845	1.000	2.5	2.50
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total 3.82C

Spalls were small, generally less than 1 inch wide and contained no loose material. Transverse cracks noted were unsealed. Joint seal had lost bond on one side of most joints. Occasionally the joint seal was missing. See Figure 8.

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 2A  
Discrete Area PA2A-2 Total Slabs in Discrete Area (a) 3721  
No. of Slabs Sampled (b) 189 Ratio a/b = 19.7

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect: c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	3	59	0.016	7.5	0.12
Scaling					
Shattered Slab					
Joint Seal	189	3721	1.000	2.5	2.50
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total
Joint seal was hard and loose. Some portions of the sealant were completely missing. Corner spalls noted were generally less than 2 inches on a side.					2.62C

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 2-A  
Discrete Area PA2A-3 Total Slabs in Discrete Area (a) 416  
No. of Slabs Sampled (b) 104 Ratio a/b = 4.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect: c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*	4	16	0.038	1.0	0.04
I.C.**					
Depression					
Spalling	34	136	0.327	7.5	2.45
Scaling					
Shattered Slab					
Joint Seal	104	416	1.000	2.5	2.50
Pumping					
"D-line" cracking					

Remarks on Pavement Condition \_\_\_\_\_ Total 4.99C ...

Joint seal was hardened and missing in many locations. Weeds were growing in some joints. Spalls were up to 6 inches wide and 10 feet long. See Figure 9.

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 2-A

Discrete Area PA2A-4 Total Slabs in Discrete Area (a) 164

No. of Slabs Sampled (b) 41 Ratio a/b = 4.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*					
I.C.**					
Depression					
Spalling	31	124	0.756	7.5	5.67
Scaling					
Shattered Slab					
Joint Seal	41	164	1.000	2.5	2.50
Pumping					
"D-line" cracking					

Remarks on Pavement Condition \_\_\_\_\_ Total 8.17C \*\*\*

Spalls ranged up to 6" wide and 8 feet long. Loose chunks were noted in most spalls. Joint seal was almost completely gone. See Figure 10.

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement



PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 3A  
Discrete Area PA3A-1 Total Slabs in Discrete Area (a) 900  
No. of Slabs Sampled (b) 180 Ratio a/b = 5.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break	3	15	0.017	2.5	0.04
L.C. or T.C.*	5	25	0.028	1.0	0.03
I.C.**					
Depression					
Spalling	21	105	0.117	7.5	0.88
Scaling					
Shattered Slab					
Joint Seal	180	900	1.000	2.5	2.50
Pumping					
"D-line" cracking					

Remarks on Pavement Condition \_\_\_\_\_ Total 3.45C ...

Joint seal was completely missing in strips up to 10 feet long. Other joints contained embedded stones. Spalls were up to 3 inches wide and 4 feet long. Most cracks were unsealed. Numerous slabs had been spalled by jet blast, however all jet blast spalls were successfully repaired.

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 4  
Discrete Area PA4-3 Total Slabs in Discrete Area (a) 244  
No. of Slabs Sampled (b) 61 Ratio a/b = 4.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L C or T C *	12	48	0.197	1.0	0.20
I C **					
Depression					
Spalling	13	52	0.213	7.5	1.60
Scaling					
Shattered Slab	3	12	0.049	9.0	0.44
Joint Seal	61	244	1.000	2.5	2.50
Pumping					
"D-line" cracking					
Remarks on Pavement Condition					Total 4.74C ***
This discrete area contained many slabs of varying sizes. Most cracks and shattered slabs appeared to be caused by the odd slab sizes. Joint seal was hardened and had lost bond.					

- \* Longitudinal crack or Transverse crack
- \*\* Intersecting crack
- \*\*\* Letter suffix "C" represents PCC pavement

PORTLAND CEMENT CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 4  
Discrete Area PA4-4 Total Slabs in Discrete Area (a) 15  
No. of Slabs Sampled (b) 15 Ratio a/b = 1.0

Defect Type	No. of Sample Slabs w/Defect	Total Slabs w/Defect: c x a/b	Defect Density (per slab) d/a	Defect Severity Weight	Weighted Defect Density e x f
	(c)	(d)	(e)	(f)	(g)
Faulting					
Corner Break					
L.C. or T.C.*	10	10	0.667	1.0	0.67
I.C.**					
Depression					
Spalling	5	5	0.333	7.5	2.50
Scaling					
Shattered Slab	4	4	0.267	9.0	2.40
Joint Seal	15	15	1.000	2.5	2.50
Pumping					
"D-line" cracking					
Remarks on Pavement Condition_____Total					8.07C...
The 60' x 60' slabs had cracked into several pieces. All cracks were unsealed. Spalls were up to 6 inches wide. See Figure 11.					

\* Longitudinal crack or Transverse crack  
\*\* Intersecting crack  
\*\*\* Letter suffix "C" represents PCC pavement

**BLANK PAGE**

ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Runway 3-21  
Discrete Area R3-1 Area of Discrete Area (a) 650,000 ft<sup>2</sup>  
No. of Sample Areas (b) 15 Ratio: (a/2500b) 17.3

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq ft) 10 d/a	Defect Severity Weight	Weighted Defect Density (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*					
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking					
Rutting					
Raveling					
Erosion - Jet Blast					
Oil Spillage					
Broken-up Area					
Total					0.00A
Remarks on Pavement Condition					
The surface aggregate of the 1967 overlay was just beginning to become exposed. No measurable defects were found. See Figure 12.					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack  
\*\* Letter suffix "A" indicates asphaltic pavement



# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Runway 9-27  
Discrete Area R9-1 Area of Discrete Area (a) 448,400 ft<sup>2</sup>  
No. of Sample Areas (b) 15 Ratio: (a/2500b) 12.0

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density: (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	495 ft.	5940 ft.	0.132	2.5	0.33
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking	1107 ft. <sup>2</sup>	13284 ft. <sup>2</sup>	0.296	2.5	0.74
Rutting					
Raveling					
Erosion-Jet Blast					
Oil Spillage					
Broken-up Area					
Total					1.07A
<p align="center"><b>Remarks on Pavement Condition</b></p> <p>The pattern cracking was less than 1/16 inch wide and appeared to be shrinkage cracks. Longitudinal construction joint cracks were open to a maximum width of 1/8 inch. See Figure 13.</p>					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack.  
\*\* Letter suffix "A" indicates asphaltic pavement

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Runway 9-27  
 Discrete Area R9-2 Area of Discrete Area (a) 52,500 ft<sup>2</sup>  
 No. of Sample Areas (b) 5 Ratio: (a/2500b) 4.2

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ *					
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking					
Rutting					
Raveling					
Erosion-Jet Blast					
Oil Spillage					
Broken-up Area					
Total					0.00A
Remarks on Pavement Condition  No defects were noted in the overlay placed in 1967.					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack  
 \*\* Letter suffix "A" indicates asphaltic pavement

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Taxiway 3  
 Discrete Area T3-1 Area of Discrete Area (a) 257,900 ft<sup>2</sup>  
 No. of Sample Areas (b) 15 Ratio: (a/2500b) 6.9

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density: (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	190 ft.	1311 ft.	0.051	2.5	0.13
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking	80 ft. <sup>2</sup>	552 ft. <sup>2</sup>	0.021	2.5	0.05
Rutting					
Reveling					
Erosion- Jet Blast					
Oil Spillage	625 ft. <sup>2</sup>	4313 ft. <sup>2</sup>	0.167	1.5	0.25
Broken-up Area					
Total					0.43A
Remarks on Pavement Condition					
<p>Longitudinal construction joint cracks were open less than 1/16 inch. Pattern cracking occurred along longitudinal construction joints and was unsealed. A strip of oil or fuel spillage has softened the slurry seal slightly. Some slight depressions which were not deep enough to include in the tally survey were found. See Figure 14.</p>					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack.

\*\* Letter suffix "A" indicates asphaltic pavement

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Taxiway 9-27  
Discrete Area T9-1 Area of Discrete Area (a) 217,400 ft<sup>2</sup>  
No. of Sample Areas (b) 15 Ratio: (a/2500b) 5.8

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq ft) 10 d/a	Defect Severity Weight	Weighted Defect Density (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	300 ft.	1740 ft.	0.080	2.5	0.20
Reflection Crack					
Faulting		1000 ft.***	0.046	8.5	0.39
Patching		64 ft.***	0.003	3.0	0.01
Settlement or Depression		124 ft.***	0.006	9.0	0.05
Pattern Cracking	140 ft. <sup>2</sup>	812 ft. <sup>2</sup>	0.037	2.5	0.09
Rutting					
Reveling					
Erosion-Jet Blast					
Oil Spillage					
Broken-up Area					
Total					0.74A
Remarks on Pavement Condition  Longitudinal construction joint cracks were open a maximum of 1/8 inch. Patching and settlement occurred where test pits were made. Faulting to a maximum displacement of 2 inches was along Parking Apron 1A. See Figure 15.					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack

\*\* Letter suffix "A" indicates asphaltic pavement

\*\*\*Singular defects

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Connecting Taxiway 2  
 Discrete Area CT2-1 Area of Discrete Area (a) 17,500 ft<sup>2</sup>  
 No. of Sample Areas (b) 2 Ratio: (a/2500b) 3.5

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density: (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*					
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking					
Rutting					
Raveling					
Erosion-Jet Blast					
Oil Spillage					
Broken-up Area					
Total					0.00A
Remarks on Pavement Condition  No defects were visible.					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack.  
 \*\* Letter suffix - A - indicates asphaltic pavement

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Connecting Taxiway 3  
 Discrete Area CT3-1 Area of Discrete Area (a) 17,500 ft<sup>2</sup>  
 No. of Sample Areas (b) 2 Ratio: (a/2500b) 3.5

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects: (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density: (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*					
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking					
Rutting					
Raveling					
Erosion—Jet Blast					
Oil Spillage					
Broken-up Area					
Total					0.00A
Remarks on Pavement Condition					
No defects were visible.					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack.

\*\* Letter suffix "A" indicates asphaltic pavement.

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Connecting Taxiway 7  
 Discrete Area CT7-1 Area of Discrete Area (a) 27,500 ft<sup>2</sup>  
 No. of Sample Areas (b) 3 Ratio: (a/2500b) 3.7

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density: (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	60 ft.	222 ft.	0.081	2.5	0.20
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking	600 ft. <sup>2</sup>	2220 ft. <sup>2</sup>	0.807	2.5	2.02
Rutting					
Raveling	100 ft. <sup>2</sup>	370 ft. <sup>2</sup>	0.135	7.0	0.95
Erosion-Jet Blast					
Oil Spillage					
Broken up Area					
Total					3.17A
Remarks on Pavement Condition  Pattern cracking was unsealed and in blocks of 1' x 2'. Longitudinal construction joint cracks were open 1/8 inch. Raveling occurred with the pattern cracking and was 1/2 to 1 inch deep.					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack.

\*\* Letter "A" indicates asphaltic pavement.



# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Connecting Taxiway 8  
Discrete Area CT8-1 Area of Discrete Area (a) 18,000 ft<sup>2</sup>  
No. of Sample Areas (b) 2 Ratio: (a/2500b) 3.6

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	100 ft.	360 ft.	0.200	2.5	0.50
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking	150 ft. <sup>2</sup>	540 ft. <sup>2</sup>	0.300	2.5	0.75
Rutting					
Raveling					
Erosion-Jet Blast					
Oil Spillage					
Broken-up Area					
Total					1.25A
Remarks on Pavement Condition  Longitudinal construction joints were open approximately 1/8 inch. Pattern cracking was in 1 foot blocks.					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack  
\*\* Letter suffix "A" indicates asphaltic pavement

ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Connecting Taxiway 9  
Discrete Area CT9-1 Area of Discrete Area (a) 18,000 ft<sup>2</sup>  
No. of Sample Areas (b) 2 Ratio: (a/2500b) 3.6

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density: (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	150 ft.	540 ft.	0.300	2.5	0.75
Reflection Crack					
Faulting					
Patching		16 ft. <sup>2</sup> / <sub>2500</sub>	0.009	3.0	0.03
Settlement or Depression		16 ft. <sup>2</sup> / <sub>2500</sub>	0.009	9.0	0.08
Pattern Cracking	60 ft. <sup>2</sup>	216 ft. <sup>2</sup>	0.120	2.5	0.30
Rutting					
Raveling					
Erosion- Jet Blast					
Oil Spillage					
Broken-up Area					
Total					1.16A
Remarks on Pavement Condition					
Longitudinal construction joint cracks were open to a maximum width of 1/8 inch. Patching and settlement was at a test pit location.					

\* T.C. = Transverse Crack, L.C. = Longitudinal Crack, LCJ = Longitudinal Construction Joint  
ft. = feet, sq. ft. = square feet, ft. <sup>2</sup> = square feet

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Connecting Taxiway A  
Discrete Area CTA-1 Area of Discrete Area (a) 43,300 ft<sup>2</sup>  
No. of Sample Areas (b) 4 Ratio: (a/2500b) 4.33

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects: (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density: (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	200 ft.	866 ft.	0.200	2.5	0.50
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking	5250 ft. <sup>2</sup>	22,733 ft. <sup>2</sup>	5.25	2.5	13.13
Rutting					
Raveling					
Erosion-Jet Blast					
Oil Spillage					
Broken-up Area					
Total					13.63A
<b>Remarks on Pavement Condition</b>  Pattern cracking was in approximately 1 foot blocks and was unsealed. The cracks were generally less than 1/16 inch wide. Longitudinal construction joints were open to 1/8 inch. Little of the slurry seal was remaining. See Figure 16.					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack.

\*\* Letter suffix "A" indicates asphaltic pavement

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Connecting Taxiway B  
 Discrete Area CTB-1 Area of Discrete Area (a) 15,000 ft<sup>2</sup>  
 No. of Sample Areas (b) 2 Ratio: (a/2500b) 3.0

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density: (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	300 ft.	900 ft.	0.600	2.5	1.50
Reflection Crack					
Faulting					
Patching					
Settlement or Depression	500 ft. <sup>2</sup>	1500 ft. <sup>2</sup>	1.000	9.0	9.00
Pattern Cracking	1500 ft. <sup>2</sup>	4500 ft. <sup>2</sup>	3.000	2.5	7.50
Rutting					
Raveling					
Erosion--Jet Blast					
Oil Spillage					
Broken-up Area					
Total					18.00A
Remarks on Pavement Condition  Connecting Taxiway B has apparently received no maintenance and is rarely used. Cracks were open to 1/2 inch. The depressions were 1 inch deep.					

- \* Transverse crack, longitudinal crack or longitudinal construction joint crack.  
 \*\* Letter in the "A" indicates asphaltic pavement

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Connecting Taxiway C  
 Discrete Area CTC-1 Area of Discrete Area (a) 7,500 ft<sup>2</sup>  
 No. of Sample Areas (b) 1 Ratio: (a/2500b) 3.0

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/b	Defect Severity Weight	Weighted Defect Density (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*					
Reflection Crack					
Faulting					
Patching					
Settlement or Depression		16 ft.2***	0.021	9.0	0.19
Pattern Cracking					
Rutting					
Raveling					
Erosion-Jet Blast					
Oil Spillage					
Broken-up Area					

Total 0.19A

## Remarks on Pavement Condition

Connecting Taxiway C has received little or no maintenance. Surface aggregate was exposed. The depression noted was at test pit.

\* Transverse crack, longitudinal crack or longitudinal construction joint crack

\*\* Letter suffix "A" indicates asphaltic pavement

\*\*\* Singular defect.

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 2  
 Discrete Area PA2-1 Area of Discrete Area (a) 346,496 ft<sup>2</sup>  
 No. of Sample Areas (b) 15 Ratio (a/2500b) 9.2

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) = Ratio	Defect Density (per 10 sq. ft.) 10 d	Defect Severity Weight	Weighted Defect Density (d) = (f)
	(c)	(d)	(e)	(f)	(g)
T.C. LC or LCJ*	2395 ft.	22034 ft.	0.636	2.5	1.59
Reflection Cracks					
Faulting					
Patching					
Settlement or Depression	30 ft. <sup>2</sup>	276 ft. <sup>2</sup>	0.008	9.0	0.07
Pattern Cracking	1996 ft. <sup>2</sup>	18363 ft. <sup>2</sup>	0.530	2.5	1.33
Rutting					
Raveling					
Erosion Jet Blast					
Oil Spillage	200 ft. <sup>2</sup>	1840 ft. <sup>2</sup>	0.053	1.5	0.08
Broken up Area					
Total					3.07A

Remarks on Pavement Condition

Longitudinal construction joint, transverse, and pattern cracking was open 1/4 to 1/2 inch. The oil spillage had softened the pavement surface. A test pit patch settled nearly 1 inch. See Figure 17.

\* T.C. = transverse crack; longitudinal crack or longitudinal construction joint crack  
 \*\* LCJ = Lateral Construction Joint. A indicates asphaltic pavement

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 3  
Discrete Area PA3-1 Area of Discrete Area (a) 111,150 ft<sup>2</sup>  
No of Sample Areas (b) 10 Ratio (a/2500b) 4.5

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	549 ft.	2471 ft.	0.222	2.5	0.56
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking	3185 ft. <sup>2</sup>	14333 ft. <sup>2</sup>	1.290	2.5	3.23
Rutting					
Raveling					
Erosion Jet Blast					
Oil Spillage	900 ft. <sup>2</sup>	4050 ft. <sup>2</sup>	0.364	1.5	0.55
Broken up Area					
Total					4.34A
Remarks on Pavement Condition					
<p>Longitudinal construction joint cracks were open to a maximum width of 1/4 inch. Pattern cracking was in 1 to 3 foot polygons. See Figure 18.</p>					

\* Transverse crack, longitudinal crack or longitudinal construction joint crack  
\*\* Letter suffix "A" indicates asphaltic pavement



# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 4  
Discrete Area PA4-1 Area of Discrete Area (a) 320,000 ft<sup>2</sup>  
No. of Sample Areas (b) 15 Ratio (a/2500b) 8.5

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq ft) 10 d/a	Defect Severity Weight	Weighted Defect Density (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	1195 ft.	10158 ft.	0.317	2.5	0.79
Reflection Crack					
Faulting					
Patching	250 ft. <sup>2</sup>	2125 ft. <sup>2</sup>	0.066	3.0	0.20
Settlement or Depression	245 ft. <sup>2</sup>	2083 ft. <sup>2</sup>	0.065	9.0	0.59
Pattern Cracking	11541 ft. <sup>2</sup>	97334 ft. <sup>2</sup>	3.041	2.5	7.60
Rutting					
Raveling	1000 ft. <sup>2</sup>	8500 ft. <sup>2</sup>	0.266	7.0	1.86
Erosion-Jet Blast					
Oil Spillage					
Broken-up Area					
Total					11.04A

## Remarks on Pavement Condition

Pattern cracking was in blocks ranging in size from 6 inches to 5 feet. Pattern cracking was unsealed. Raveling occurred in conjunction with pattern cracking and was 1" deep. Longitudinal and longitudinal construction joint cracks were open to a maximum width of 1/4". Settled areas were up to 1" deep. See Figure 19.

\* Transverse crack, longitudinal crack or longitudinal construction joint crack

\*\* (a) = 11.04A indicates asphalt pavement

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 4  
 Discrete Area PA4-2 Area of Discrete Area (a) 40,200 ft<sup>2</sup>  
 No of Sample Areas (b) 2 Ratio (a/2500b) 8.04

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) = Ratio	Defect Density (per 10 sq ft) 10 d/a	Defect Severity Weight	Weighted Defect Density (c) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C. L.C. or L.C.J.*	900 ft.	7236 ft.	1.8	2.5	4.50
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking	400 ft. <sup>2</sup>	3216 ft. <sup>2</sup>	0.80	2.5	2.00
Rutting					
Revealing					
Erosion - Jet Blast					
Oil Spillage					
Broken up Area					
Total					6.50A

## Remarks on Pavement Condition

Transverse, longitudinal, and longitudinal construction joint cracks occurred equally and were open to 1/2" wide. Pattern cracking was in large 4 x 5 feet blocks and appeared to be caused by shrinkage of the epoxy asphaltic surfacing. See Figure 20.

\* Transverse, longitudinal, and longitudinal construction joint cracks occurred equally and were open to 1/2" wide. Pattern cracking was in large 4 x 5 feet blocks and appeared to be caused by shrinkage of the epoxy asphaltic surfacing. See Figure 20.

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 5  
 Discrete Area PAS-1 Area of Discrete Area (a) 240,125 ft<sup>2</sup>  
 No. of Sample Areas (b) 14 Ratio (a/2500b) 6.9

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density (e) x (f)
	(c)	(d)	(e)	(f)	(g)
TC LC or LCJ*	1325 ft.	9143 ft.	0.381	2.5	0.95
Reflection Cracks					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking	5260 ft. <sup>2</sup>	36294 ft. <sup>2</sup>	1.511	2.5	3.78
Rutting	1330 ft. <sup>2</sup>	9177 ft. <sup>2</sup>	0.382	9.0	3.44
Raveling					
Erosion Jet Blast					
Oil Spillage					
Broken up Area					
Total					8.17A

## Remarks on Pavement Condition

Longitudinal construction joint and transverse cracks were open 1/8". Pattern cracking was in polygons ranging from 6 inches to 2 feet. Rutting was up to 1 inch deep and occurred where a B47 taxi onto Parking Apron 3A. See Figure 21.

\* TC = transverse crack; LC = longitudinal crack; LCJ = longitudinal construction joint crack  
 A = calculated significant pavement

# **ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY**

Airfield NAS Point Mugu Facility Parking Apron 6  
 Discrete Area PA6-1 Area of Discrete Area (a) 366,250 ft<sup>2</sup>  
 No. of Sample Areas (b) 15 Ratio: (a/2500b) 9.8

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects: (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density: (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*	640 ft.	6272 ft.	0.171	2.5	0.43
Reflection Crack					
Faulting					
Patching	16 ft. <sup>2</sup>	157 ft. <sup>2</sup>	0.004	3.0	0.01
Settlement or Depression					
Pattern Cracking	5790 ft. <sup>2</sup>	56742 ft. <sup>2</sup>	1.549	2.5	3.87
Rutting					
Reveling	160 ft. <sup>2</sup>	1568 ft. <sup>2</sup>	0.043	7.0	0.30
Erosion-Jet Blast					
Oil Spillage	250 ft. <sup>2</sup>	2450 ft. <sup>2</sup>	0.067	1.5	0.10
Broken-up Area					
Total					4.71A

## **Remarks on Pavement Condition**

Pattern cracking was in blocks ranging from 6 inches to 2 feet on each side. Most of the pattern cracking was near the Air Force area. Longitudinal instruction joint cracks were open 1/8 inch. Oil spillage has definitely softened the pavement surface.

\* Transverse crack, longitudinal crack or longitudinal construction joint crack.

\*\* Letter suffix "A" indicates asphaltic pavement.

# ASPHALTIC CONCRETE DISCRETE AREA DEFECT SUMMARY

Airfield NAS Point Mugu Facility Parking Apron 6  
 Discrete Area PA6-2 Area of Discrete Area (a) 107,400 ft<sup>2</sup>  
 No. of Sample Areas (b) 10 Ratio (a/2500b) 4.3

Defect Type	Length or Area of Sampled Defects	Total Length or Area of All Defects (c) x Ratio	Defect Density (per 10 sq. ft.) 10 d/a	Defect Severity Weight	Weighted Defect Density (e) x (f)
	(c)	(d)	(e)	(f)	(g)
T.C., L.C. or LCJ*					
Reflection Crack					
Faulting					
Patching					
Settlement or Depression					
Pattern Cracking		*** 107400 ft. <sup>2</sup>	10.000	2.5	25.00
Rutting					
Raveling					
Erosion-Jet Blast					
Oil Spillage	2500 ft. <sup>2</sup>	10750 ft. <sup>2</sup>	1.000	1.5	1.50
Broken-up Area					
Total					26.50A

## Remarks on Pavement Condition

This discrete area had a fog seal of some type applied which had apparently resulted in surface pattern cracking. The cracking was in uniform polygons of approximately 1 square foot. Oil or fuel spillage had softened the surface sufficiently to allow aggregate to be dislodged by hand. See Figures 22 and 23.

\* Transverse crack, longitudinal crack or longitudinal construction joint crack

\*\* Letter suffix "A" indicates asphaltic pavement

\*\*\*Entire area is pattern cracked.

PORTLAND CEMENT AND ASPHALTIC CONCRETE  
FACILITY DEFECT SUMMARY SHEETS

# PORTLAND CEMENT CONCRETE FACILITY DEFECT SUMMARY

Airfield NAS Point Mugu, California

Date Surveyed August 1970

Facility for portland	Weighted Defect Density Total	Ratio Discrete Area Total Facility Area*	Average Weighted Defect Density (a) x (b)
	(a)	(b)	(c)**
Figures 10-11			
8-1-1	3.34C	0.22	1.17
8-1-2	2.25C	0.78	1.76
			2.93C
Figures 10-12			
8-1-3	0.22C	1.00	0.22C
Figures 10-13			
7-1-1	3.64C	1.00	3.64C
Figures 10-14			
7-1-2	0.43C	1.00	0.43C
Figures 10-15			
7-1-3	0.33C	1.00	0.33C
Continued Fig 10-16			
7-1-4	4.63C	1.00	4.63C
Continued Fig 10-17			
7-1-5	3.07C	1.00	3.07C
Figures 10-18			
7-1-6	4.63C	1.00	4.63C

\* If facility is not a discrete area of PCC, the ratio of discrete area to total facility area is 1.00. If facility is a discrete area of PCC, the ratio of discrete area to total facility area is the ratio of discrete area to total facility area.

\*\* The average weighted defect density is the sum of the weighted defect densities divided by the sum of the weighted defect densities.

ENDING PAGE BLANK



PORTLAND CEMENT CONCRETE FACILITY DEFECT SUMMARY Airfield <u>NAS Point Mugu, California</u> Date Surveyed <u>August 1970</u>			
Facility (or portion)	Weighted Defect Density Total	Ratio <u>Discrete Area</u> Total Facility Area*	Average Weighted Defect Density (a) x (b)
	(a)	(b)	(c)**
Parking Apron 2 PA2-2	4.57C	1.00	4.57C
Parking Apron 2A			
PA2A-1	3.82C	0.30	1.15
PA2A-2	2.62C	0.60	1.57
PA2A-3	4.99C	0.07	0.35
PA2A-4	8.17C	0.03	<u>0.25</u>
			3.32C
Parking Apron 3A			
PA3A-1	3.45C	1.00	3.45C
Parking Apron 4			
PA4-3	4.74C	0.66	3.13
PA4-4	8.07C	0.34	<u>2.74</u>
			5.87C

\* If facility entirely constructed of PCC, indicates total facility area. If facility only partly constructed of PCC, indicates total area of PCC portion of facility.

\*\* Letter suffix "C" on average weighted defect densities indicates Portland cement concrete pavements.

ASPHALTIC CONCRETE FACILITY DEFECT SUMMARY Airfield <u>NAS Point Mugu, California</u> Date Surveyed <u>August 1970</u>			
Facility (or portion)	Weighted Defect Density Total	Ratio: <u>Discrete Area</u> Total Facility Area*	Average Weighted Defect Density (a) x (b)
	(a)	(b)	(c)**
Runway 3-21 R3-1	0.00A	1.00	0.00A
Runway 9-27 R9-1	1.07A	0.90	0.96
R9-2	0.00A	0.10	<u>0.00</u> 0.96A
Taxiway 3 T3-1	0.43A	1.00	0.43A
Taxiway 9-27 T9-1	0.74A	1.00	0.74A
Connecting Taxiway 2 CT2-1	0.00A	1.00	0.00A
Connecting Taxiway 3 CT3-1	0.00A	1.00	0.00A
Connecting Taxiway 7 CT7-1	3.17A	1.00	3.17A

\* If facility entirely constructed of AC, indicates total facility area. If facility only partly constructed of AC, indicates total area of AC portion of facility.

\*\* Letter suffix "A" on average weighted defect densities indicates asphaltic concrete pavements.

ASPHALTIC CONCRETE FACILITY DEFECT SUMMARY Airfield <u>NAS Point Mugu, California</u> Date Surveyed <u>August 1970</u>			
Facility (or portion)	Weighted Defect Density Total	Ratio <u>Discrete Area</u> Total Facility Area*	Average Weighted Defect Density (a) x (b)
	(a)**	(b)	(c)**
Connecting Taxiway 8 CT8-1	1.25A	1.00	1.25A
Connecting Taxiway 9 CT9-1	1.16A	1.00	1.16A
Connecting Taxiway A CTA-1	13.63A	1.00	13.63A
Connecting Taxiway B CTB-1	18.00A	1.00	18.00A
Connecting Taxiway C CTC-1	0.19A	1.00	0.19A
Parking Apron 2 PA2-1	3.07A	1.00	3.07A
Parking Apron 3 PA3-1	4.34A	1.00	4.34A

\* If facility entirely constructed of AC, indicates total facility area. If facility only partly constructed of AC, indicates total area of AC portion of facility.

\*\* Letter suffix "A" on weighted defect densities indicates asphaltic concrete pavements.

ASPHALTIC CONCRETE FACILITY DEFECT SUMMARY Airfield <u>NAS Point Mugu, California</u> Date Surveyed <u>August 1970</u>			
Facility (or portion)	Weighted Defect Density Total	Ratio: <u>Discrete Area</u> Total Facility Area*	Average Weighted Defect Density (a) x (b)
	(a)**	(b)	(c)**
Parking Apron 4			
PA4-1	11.04A	0.89	9.83
PA4-2	6.50A	0.11	<u>0.72</u>
			10.55A
Parking Apron 5			
PA5-1	8.17A	1.00	8.17A
Parking Apron 6			
PA6-1	4.71A	0.77	3.63
PA6-2	26.50A	0.23	<u>6.10</u>
			9.73A

\* If facility entirely constructed of AC, indicates total facility area. If facility only partly constructed of AC, indicates total area of AC portion of facility.

\*\* Letter suffix "A" on weighted defect densities indicates asphaltic concrete pavements.

**Appendix A**  
**CONSTRUCTION HISTORY**

**BLANK PAGE**

Appendix A

CONSTRUCTION HISTORY FOR SAS PT. MARY, California

Item No.	Section from Surface to Subgrade	Date Constructed	Date Strengthened or Sealed
1	Portions of Runway 2-21 and Taxiway 21		
	11" Portland cement concrete	1960	
	12" Subbase (CB 40 @ 9%)	1960	
2	Portions of Runway 2-21		
	11" Portland cement concrete	1960	
	12" Subbase (CB 40 @ 9%)	1960	
3	Portions of Runway 2-21, Taxiway 2 and Connecting Taxiway A		
	10" Portland cement concrete	1962	
	(seal/surf)		
	4" Base course	1962	
4	Portion of Runway 2-21		
	1" Asphaltic concrete		1967
	Fog seal		1966
	Slurry seal		1962
	1" Asphaltic concrete	1962	
	9" Crushed run base	1962	



Appendix A

CONSTRUCTION HISTORY FOR NAS Pt. Mugu, California

Item No.	Section From Surface to Subgrade	Date Constructed	Date Strengthened or Sealed
5	Portion of Runway 3-21		
	2" Asphaltic concrete		1967
	10g seal		1966
	Slurry seal		1963
	3" Asphaltic concrete	1952	
	12" Crusher run base	1952	
6	Portion of Taxiway 2 and all of Connecting Taxiway 2		
	Slurry seal		1963
	3" Asphaltic concrete	1952	
	9" Crusher run base	1952	
7	Portion of Taxiway 3 and all of connecting Taxiway 3		
	Slurry seal		1963
	3" Asphaltic concrete	1952	
	12" Crusher run base	1952	
8	Portion of Connecting Taxiway A		
	Slurry seal		1963
	3" Asphaltic concrete	1952	
	12" Crusher run base	1952	

# Appendix A

## CONSTRUCTION HISTORY FOR NAS Pt. Mugu, California

Item No.	Section From Surface to Subgrade	Date Constructed	Date Strengthened or Sealed
9	Portions of Runway 9-27, Taxiway 9-27,		
	Connecting Taxiway 7, and Parking Apron		
	2A.		
	Joints sealed (Runway 9-27 and Taxiway		1968
	9-27 only).		
	10" Portland cement concrete	1950	
	2" Stabilized base	1950	
	12" Dredged sand fill	1950	
10	Portion of Runway 9-27		
	2" Asphaltic concrete		1967
	Fog seal		1966
	Slurry seal		1963
	3" Asphaltic concrete		1950
	9" Stabilized		1950
	6" Dredged sand		
	Marston matting	1944	
	8" Pit run base	1944	

Appendix A

CONSTRUCTION HISTORY FOR NAS Pt. Mugu, California

Item No.	Section From Surface to Subgrade	Date Constructed	Date Strengthened or Sealed
11	Portion of Runway 9-27		
	Fog seal		1966
	Slurry seal		1963
	3" Asphaltic concrete		1950
	6" Stabilized base		1950
	6" Dredged sand		1950
	Marston matting	1944	
	8" Pit run base	1944	
12	Portion of Runway 9-27		
	Fog seal		1966
	Slurry seal		1963
	3" Asphaltic concrete		1950
	9" Stabilized base		1950
	6" Dredged sand		1950
	Marston matting	1944	
	8" Pit run base	1944	
13	Portion of Taxiway 9-27		
	10" Portland cement concrete	1957	
	8" Stabilized base	1957	
	6" Dredged sand	1957	

Appendix A

CONSTRUCTION HISTORY FOR RAIL PL. 1948, California

Item No.	Section from Surface to Subgrade	Date Constructed	Date Stripped Forward or Rebuilt
14	Portions of Railway 7-22 and Connecting Railway 1 and all of Connecting Railways 8 and 9.		
	Top soil		1946
	Slurry seal		1947
	4" Asphaltic concrete	1950	
	8" Stabilized Base	1950	
	6" Dredged sand	1950	
15	Parking Apron 3A		
	10" Portland cement concrete	1952	
	4" Crusher run base	1952	
	6" Subbase - 100%	1952	
	6" Subbase - 85%	1952	
	6" Native material	1952	
16	Parking Apron 3, Connecting Railway 8, and a portion of Parking Apron 1.		

Appendix A

CONSTRUCTION HISTORY FOR Box 21, House, California

Item No.	Section from Surface to Subgrade	Date Constructed	Date Strengthened or Sealed
11	Section of Footing System 1A		
	10" Densest compacted aggregate	1934	
	(reinforced)		
	6" crushed run stone	1934	
	6" crushed sand	1934	
12	Section of Footing System 1		
	Similar to 11		1934
	7" aggregate compacted	1932	
	8" base of 211	1932	
	4" surface of 211	1932	
	4" surface material	1932	
13	Section of Footing System 1A		
	12" Densest compacted aggregate	1934	
	8" surface	1942	
	4" compacted subgrade	1942	
14	Section of Footing System 1		
	7" aggregate compacted	1932	
	8" base compacted	1942	
	4" compacted and seal coat material	1942	

Appendix A

CONSTRUCTION HISTORY FOR MAS Pt. Mugu, California

Item No.	Section From Surface to Subgrade	Date Constructed	Date Strengthened or Sealed
21	All of Parking Apron 1A and Apron Connecting Taxiways		
	11" Portland cement concrete	1960	
	11" Compacted base	1960	
	6" Native material	1960	
22	Portion of Parking Apron 2A		
	11" Portland cement concrete	1961	
	11" Compacted base	1961	
	6" Native fill	1961	
23	Portions of Parking Aprons 2, 3, and 4.		
	Slurry seal		1963
	3" Asphaltic concrete	1953	
	8" Crusher run base	1953	
24	Portion of Parking Aprons 1, 2, and 4.		
	Portland cement concrete, no construction information available.		

Appendix A

CONSTRUCTION HISTORY FOR NAS Pt. Mugu, California


Item No.	Section From Surface to Subgrade	Date Constructed	Date Strengthened or Sealed
25	Portion of Parking Apron 4		
	Slurry seal		1963
	4" Asphaltic concrete	1953	
	8" Base course	1953	
	8" Subbase	1953	
26	Portions of Parking Aprons 1 and 4		
	Slurry seal	-	1963
	3" Asphaltic concrete	1960	
	9" Select base - 60CBR	1960	
	6" Subbase - 30CBR	1960	
	6" Compacted native material	1960	
27	Portion of Parking Apron 6		
	3" Asphaltic concrete	1959	
	10" Select base	1959	
28	Portion of Parking Apron 6		
	10" Portland cement concrete	1961	
	10" Base	1961	
	6" Compacted native	1961	

## Appendix A

## CONSTRUCTION HISTORY FOR NAS Pt. Mugu, California

[illegible]





1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	2101	2102	2103	2104	2105	2106	2107	2108	2109	2110	2111	2112	2113	2114	2115	2116	2117	2118	2119	2120	2121	2122	2123	2124	2125	2126	2127	2128	2129	2130	2131	2132	2133	2134	2135	2136	2137	2138	2139	2140	2141	2142	2143	2144	2145	2146	2147	2148	2149	2150	2151	2152	2153	2154	2155	2156	2157	2158	2159	2160	2161	2162	2163	2164	2165	2166	2167	2168	2169	2170	2171	2172	2173	2174	2175	2176	2177	2178	2179	2180	2181	2182	2183	2184	2185	2186	2187	2188	2189	2190	2191	2192	2193	2194	2195	2196	2197	2198	2199	2200	2201	2202	2203	2204	2205	2206	2207	2208	2209	2210	2211	2212	2213	2214	2215	2216	2217	2218	2219	2220	2221	2222	2223	2224	2225	2226	2227	2228	2229	2230	2231	2232	2233	2234	2235	2236	2237	2238	2239	2240	2241	2242	2243	2244	2245	2246	2247	2248	2249	2250	2251	2252	2253	2254	2255	2256	2257	2258	2259	2260	2261	2262	2263	2264	2265	2266	2267	2268	2269	2270	2271	2272	2273	2274	2275	2276	2277	2278	2279	2280	2281	2282	2283	2284	2285	2286	2287	2288	2289	2290	2291	2292	2293	2294	2295	2296	2297	2298	2299	2300	2301	2302	2303	2304	2305	2306	2307	2308	2309	2310	2311	2312	2313	2314	2315	2316	2317	2318	2319	2320	2321	2322	2323	2324	2325	2326	2327	2328	2329	2330	2331	2332	2333	2334	2335	2336	2337	2338	2339	2340	2341	2342	2343	2344	2345	2346	2347	2348	2349	2350	2351	2352	2353	2354	2355	2356	2357	2358	2359	2360	2361	2362	2363	2364	2365	2366	2367	2368	2369	2370	2371	2372	2373	2374	2375	2376	2377	2378	2379	2380	2381	2382	2383	2384	2385	2386	2387	2388	2389	2390	2391	2392	2393	2394	2395	2396	2397	2398	2399	2400	2401	2402	2403	2404	2405	2406	2407	2408	2409	2410	2411	2412	2413	2414	2415	2416	2417	2418	2419	2420	2421	2422	2423	2424	2425	2426	2427	2428	2429	2430	2431	2432	2433	2434	2435	2436	2437	2438	2439	2440	2441	2442	2443	2444	2445	2446	2447	2448	2449	2450	2451	2452	2453	2454	2455	2456	2457	2458	2459	2460	2461	2462	2463	2464	2465	2466	2467	2468	2469	2470	2471	2472	2473	2474	2475	2476	2477	2478	2479	2480	2481	2482	2483	2484	2485	2486	2487	2488	2489	2490	2491	2492	2493	2494	2495	2496	2497	2498	2499	2500	2501	2502	2503	2504	2505	2506	2507	2508	2509	2510	2511	2512	2513	2514	2515	2516	2517	2518	2519	2520	2521	2522	2523	2524	2525	2526	2527	2528	2529	2530	2531	2532	2533	2534	2535	2536	2537	2538	2539	2540	2541	2542	2543	2544	2545	2546	2547	2548	2549	2550	2551	2552	2553	2554	2555	2556	2557	2558	2559	2560	2561	2562	2563	2564	2565	2566	2567	2568	2569	2570	2571	2572	2573	2574	2575	2576	2577	2578	2579	2580	2581	2582	2583	2584	2585	2586	2587	2588	2589	2590	2591	2592	2593	2594	2595	2596	2597	2598	2599	2600	2601	2602	2603	2604	2605	2606	2607	2608	2609	2610	2611	2612	2613	2614	2615	2616	2617	2618	2619	2620	2621	2622	2623	2624	2625	2626	2627	2628	2629	2630	2631	2632	2633	2634	2635	2636	2637	2638	2639	2640	2641	2642	2643	2644	2645	2646	2647	2648	2649	2650	2651	2652	2653	2654	2655	2656	2657	2658	2659	2660	2661	2662	2663	2664	2665	2666	2667	2668	2669	2670	2671	2672	2673	2674	2675	2676	2677	2678	2679	2680	2681	2682	2683	2684	2685	2686	2687	2688	2689	2690	2691	2692	2693	2694	2695	2696	2697	2698	2699	2700	2701	2702	2703	2704	2705	2706	2707	2708	2709	2710	2711	2712	2713	2714	2715	2716	2717	2718	2719	2720	2721	2722	2723	2724	2725	2726	2727	2728	2729	2730	2731	2732	2733	2734	2735	2736	2737	2738	2739	2740	2741	2742	2743	2744	2745	2746	2747	2748	2749	2750	2751	2752	2753	2754	2755	2756	2757	2758	2759	2760	2761	2762	2763	2764	2765	2766	2767	2768	2769	2770	2771	2772	2773	2774	2775	2776	2777	2778	2779	2780	2781	2782	2783	2784	2785	2786	2787	2788	2789	2790	2791	2792	2793	2794	2795	2796	2797	2798	2799	2800	2801	2802	2803	2804	2805	2806	2807	2808	2809	2810	2811	2812	2813	2814	2815	2816	2817	2818	2819	2820	2821	2822	2823	2824	2825	2826	2827	2828	2829	2830	2831	2832	2833	2834	2835	2836	2837	2838	2839	2840	2841	2842	2843	2844	2845	2846	2847	2848	2849	2850	2851	2852	2853	2854	2855	2856	2857	2858	2859	2860	2861	2862	2863	2864	2865	2866	2867	2868	2869	2870	2871	2872	2873	2874	2875	2876	2877	2878	2879	2880	2881	2882	2883	2884	2885	2886	2887	2888	2889	2890	2891	2892	2893	2894	2895	2896	2897	2898	2899	2900	2901	2902	2903	2904	2905	2906	2907	2908	2909	2910	2911	2912	2913	2914	2915	2916	2917	2918	2919	2920	2921	2922	2923	2924	2925	2926	2927	2928	2929	2930	2931	2932	2933	2934	2935	2936	2937	2938	2939	2940	2941	2942	2943	2944	2945	2946	2947	2948	2949	2950	2951	2952	2953	2954	2955	2956	2957	2958	2959	2960	2961	2962	2963	2964	2965	2966	2967	2968	2969	2970	2971	2972	2973	2974	2975	2976	2977	2978	2979	2980	2981	2982	2983	2984	2985	2986	2987	2988	2989	2990	2991	2992	2993	2994	2995	2996	2997	2998	2999	3000
------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------

APPENDIX A FIGURE A.1

#### REFERENCES

1. U. S. Naval Civil Engineering Laboratory. Technical Note N-761: Airfield Pavement Evaluation - USNAS Point Mugu, California, by R. J. Lowe and W. H. Chamberlin, Port Hueneme, California, Sep 1965.

Un Classified

Un Classified

Document Control Data 000

Naval Civil Engineering Laboratory  
Port Muenster, California 93061

Un Classified

AIRFIELD PAVEMENT CONDITION SURVEY, CORAL POINT WICK, CALIFORNIA

August 1970

D. J. Lambotte and R. B. Brownie

February 1971

01

73-1140

Approved for public release, distribution unlimited

Naval Facilities Engineering  
Command  
Washington, D. C. 20340

The results of a condition survey of the airfield pavements at the Naval Air Station, Port Muenster, California are presented. The survey established statistically-based condition numbers (weighted defect densities) which were direct indicators of the condition of the individual asphaltic concrete and portland cement concrete pavement facilities. Additional evaluation efforts included photographic coverage of defect types, preparation of the construction history of the station, compilation of data on current aircraft traffic and aircraft types using the station, performance of runway and taxiway tests, and a study of the requirements for future pavement evaluation efforts.

DD FORM 1473

Un Classified  
Un Classified



— — — — —

Personnel  
 Committee Survey  
 Duties  
 Policies  
 Committee Minutes

00 - 1473

Confidential